

W10 IoT Release Notes



- Notes for Release 4.04.100 (see page 3)
- Notes for Release 4.03.100 (see page 10)
- Notes for Release 4.02.100 (see page 18)
- Notes for Release 4.01.100 (see page 27)

W10 IoT Release Notes 2/31



Notes for Release 4.04.100

IGEL Universal Desktop W10

Software:	Version	4.04.100
Release Date:	2019-05-31	
Release Notes:	Version	RN-404100-1
Last update:	2019-05-31	

- Supported Devices (see page 4)
- Versions (see page 5)
- Known Issues (see page 7)
- New Features (see page 8)
- Resolved Issues (see page 9)

W10 IoT Release Notes 3 / 31



Supported Devices

Supported Devices

UD3-W10 50, UD3-W10 51

UD5-W10 50

UD6-W10 51

UD7-W10 10

UD9-W10 40, UD9-W10 Touch 41

W10 IoT Release Notes 4/31



Versions

Drivers

Drivers		
Product	Version	
Intel(R) HD Graphics	10.18.10.4425 (04/04/2016)	
Intel(R) Audio	6.16.00.3154 (09/09/2014)	
Intel(R) Trusted Execution Engine Interface	1.1.0.1064 (12/01/2014)	
Realtek High Definition Audio	6.0.1.7541 (06/18/2015)	
Realtek PCIe GBE Family Controller	10.014.0123.2017 (01/23/2017)	
AMD Radeon(TM) R3E Graphics	16.300.2501.0000 (07/26/2016)	
AMD IOIC device	1.2.0.0034 (11/08/2015)	
AMD Security Accelerator	2.22.0.0005 (06/27/2016)	
AMD GPIO v2 Controller	2.2.0.57 (04/01/2017)	
AMD SMBus device	5.12.0.0031 (04/01/2017)	
AMD Embedded Radeon E9173	23.20.808.1280 (02/14/2018)	
Applications		
Citrix Workspace App	1903	
Citrix HDX RealTime Media Engine	2.7	
Microsoft Internet Explorer	11	
Microsoft RDP Client	10.2	
NCP Enterprise Client	10.11	
Azul Zulu JAVA RE	1.8.0.212	
ThinPrint	11.0.120	
Tight VNC Server	2.8.11	
VMware Horizon Client	5.0.0	
Microsoft Windows Media Player	12	
Microsoft .NET Framework	4.6	
Adobe PDF Reader DC	15.23	
FabulaTech USB for Remote Desktop	5.2.3	

W10 IoT Release Notes 5 / 31



	IGEL WinLinux	11.01.110.13828	
•	Language Packs		
	Microsoft-Windows-Client-Language-Pack_x64_de-de.cab		
	Microsoft-Windows-Client-Language-Pack_x64_es-es.cab		
	Microsoft-Windows-Client-Language-Pack_x64_fr-fr.cab		
	Microsoft-Windows-Client-Language-Pack_x64_it-it.cab		
	Microsoft-Windows-Client-Language-Pack_x6	64_ja-jp.cab	
	Microsoft-Windows-Client-Language-Pack_x6	64_nl-nl.cab	

Microsoft Updates

microsoft Updat	es
KB4493473	
KB4493478	
KB4346087	
KB4485447	
KB4465659	
KB4132216	
KB4093137	

W10 IoT Release Notes 6/31



Known Issues

System

- Start onscreen keyboard at logon does not work.
 - The Setup setting **User Interface > Input > Keyboard > Start onscreen keyboard at logon** sets the onscreen keyboard for a logged-in user only.
 - Furthermore, the **Ease of Access** menu on welcome screen appears delayed and an error message is shown: *Could not start On-Screen keyboard <OK>*.
- VNC Maintenance screen does not work.
- Snapshot upload/download via Proxy does not work.
- Snapshot download with HTTP protocol and UMS version 5.08.100 does not work on UD7.

VMware

• When session is started via **Horizon Client**, a folder named **GPUcache** appears on the user desktop.

W10 IoT Release Notes 7 / 31



New Features

System

- Added OpenJDK Zulu from Azul 1.8.0.212.
- Added a list of installed (third party) software in IGEL Device Information.

Citrix

- Added Citrix Workspace App version 1903.
- Added Citrix HDX Realtime Media Engine version 2.7.

VMware

• Added VMware Horizon Client version 5.0.0.

W10 IoT Release Notes 8 / 31



Resolved Issues

System

- Fixed: IGEL Device Information tool does not update network information. IP address of the device will now be updated every ten seconds.
- Fixed: Session shortcuts are not deleted after removing a UMS profile or disabling Use IGEL Setup for configuring...
- Fixed: Windows Defender definitions can not be updated after deactivating the Unified Write Filter.
- Fixed: File share for downloading definition updates always disabled.
- Fixed: reboot loops while configuring the Unified Write Filter.
 Reboot loops were caused by:
 - Multiple entries with **different notations** like **c:\temp** and **C:\Temp**.
 - Incorrect notations like relative paths, e.g. /temp or temp.
- Fixed: **Snapshot** is only possible without any **whitespaces in path/filename** entry.
- Fixed: File snapshot does not work with enabled Unified Write Filter feature and plugged-in USB sticks. USB sticks have now to be removed after snapshot upload/download and before returning to Windows.

W10 IoT Release Notes 9 / 31



Notes for Release 4.03.100

IGEL Universal Desktop W10

Software:	Version	4.03.100
Release Date:	2018-11-26	
Release Notes:	Version	RN-403100-1
Last update:	2018-11-26	

W10 IoT Release Notes



Supported Devices

Supported Devices

UD3-W10 50, UD3-W10 51

UD5-W10 50

UD6-W10 51

UD7-W10 10

UD9-W10 40, UD9-W10 Touch 41

W10 IoT Release Notes 11/31



Versions

Drivers

Orivers		
Product	Version	
Intel(R) HD Graphics	10.18.10.4425 (04/04/2016)	
Intel(R) Audio	6.16.00.3154 (09/09/2014)	
Intel(R) Trusted Execution Engine Interface	1.1.0.1064 (12/01/2014)	
Realtek High Definition Audio	6.0.1.7541 (06/18/2015)	
Realtek PCIe GBE Family Controller	10.014.0123.2017 (01/23/2017)	
AMD Radeon(TM) R3E Graphics	16.300.2501.0000 (07/26/2016)	
AMD IOIC device	1.2.0.0034 (11/08/2015)	
AMD Security Accelerator	2.22.0.0005 (06/27/2016)	
AMD GPIO v2 Controller	2.2.0.57 (04/01/2017)	
AMD SMBus device	5.12.0.0031 (04/01/2017)	
AMD Embedded Radeon E9173	23.20.808.1280 (02/14/2018)	
Applications		
Citrix Workspace App	1808	
Citrix HDX RealTime Media Engine	2.6	
Microsoft Internet Explorer	11	
Microsoft RDP Client	10.2	
NCP Enterprise Client	10.11	
Sun JAVA RE	1.8 Update 40	
ThinPrint	11.0.120	
Tight VNC Server	2.8.11	
VMware Horizon Client	4.9.0	
Microsoft Windows Media Player	12	
Microsoft .NET Framework	4.6	
Adobe PDF Reader DC	15.23	
FabulaTech USB for Remote Desktop	5.2.3	
	·	

W10 IoT Release Notes 12 / 31



	IGEL WinLinux	10.06.100.10195	
•	Language Packs		
	Microsoft-Windows-Client-Language-Pack_x64_de-de.cab		
	Microsoft-Windows-Client-Language-Pack_x64_es-es.cab		
	Microsoft-Windows-Client-Language-Pack_x64_fr-fr.cab		

Microsoft-Windows-Client-Language-Pack_x64_it-it.cab

Microsoft-Windows-Client-Language-Pack_x64_ja-jp.cab

Microsoft-Windows-Client-Language-Pack_x64_nl-nl.cab

Microsoft Updates

•	microsoft opdates
	KB4462928
	KB4091644
	KB4132216
	KB4093137

W10 IoT Release Notes 13/31



Known Issues

System

- Start onscreen keyboard at logon does not work. The TC-Setup setting Userinterface > Input >
 Keyboard > Start onscreen keyboard at logon sets the onscreen keyboard for a logged in user
 only.
 - Furthermore the **Ease of Access** menu on welcome screen appears delayed and an error message is shown: *Could not start On-Screen keyboard <OK>*
- VNC Maintenance screen does not work.
- **Snapshot upload/download** via **File** protocol does not work if the USB device is plugged into a USB 3.0 port.
- Snapshot upload/download via Proxy does not work.

VMware

• When session is started via **Horizon client**, a folder named **GPUcache** appears on the user desktop.

W10 IoT Release Notes 14 / 31



New Features

System

- Added support for **UEFI Secure Boot**.
 - **IMPORTANT**: With enabled UEFI Secure Boot, it is not possible to downgrade to a W10 firmware version lower than 4.03.100!
 - https://kb.igel.com/securitysafety/uefi-secure-boot-enabling-guides-2271735.html
- Added information about current boot mode into IGEL Device Information tool (Hardware tab).
- Added information about **current Microsoft Windows activation state** into **IGEL Device Information** tool (Windows Activation tab).
- Added command to activate Windows into IGEL Device Information tool.
- Added command to save support information into IGEL Device Information tool.
- Added configuration of ForceAutoLogon. IMPORTANT: After setting "resetforceautologon" to "false" the login process can not be interrupted!
 More...

Parameter	Reset Force-Auto Logon
Registry	system.auto_logon.resetforceautologon
Value	enabled / disabled

- Added **network speed information** of Windows Client to display and use in UMS.
- Added FTP snapshot protocol.

More...

System > Update > Snapshots > Upload

System > Update > Snapshots > Download

Parameter	Server		
Registry	<pre>firmware_snapshot.ftp.server</pre>		
Parameter	Path		
Registry	<pre>firmware_snapshot.ftp.path</pre>		
Parameter Filename			
Registry	<pre>firmware_snapshot.ftp.upload_filename</pre>		
	<pre>firmware_snapshot.ftp.download_filename</pre>		
Parameter	Username		
Registry	<pre>firmware_snapshot.ftp.username</pre>		

W10 IoT Release Notes 15 / 31



Parameter Password	
Registry	<pre>firmware_snapshot.ftp.crypt_password</pre>

Parameter	Port	
Registry	<pre>firmware_snapshot.ftp.port</pre>	
Value	21	
Parameter	Proxy	
Registry	<pre>firmware_snapshot.ftp.proxy</pre>	
ParameterPort		
Registry	<pre>firmware_snapshot.ftp.proxy_port</pre>	
Value	2121	

Citrix

- Added Citrix Workspace App version 1808
- Added Citrix HDX Realtime Media Engine version 2.6

VMware

• Added VMware Horizon client version 4.8.1

VNC

• Added TightVNC Server version 2.8.11

W10 IoT Release Notes 16 / 31



Resolved Issues

System

- Fixed configured IP address is not used in IGEL Rescue Shell.
- Fixed configured **UWF exclusions results** in a bootloop.
- Fixed issues with **multi-monitor configuration** on UD7.
- Fixed UMS shutdown/reboot command does not work after disable "Prompt user on UMS actions".
- Fixed strange characters are shown when using **Swedish(Sweden)** at "Standards and Formats".
- Fixed device drivers are updated automatically when UWF is disabled on UD3.

VMware

• Fixed issues with **USB redirection**.

W10 IoT Release Notes 17 / 31



Notes for Release 4.02.100

IGEL Universal Desktop W10

Software:	Version	4.02.100
Release Date:	2018-05-11	
Release Notes:	Version	RN-402100-1
Last update:	2018-05-11	

Following formatting is used in this document:

format type	example	use
bold and underlined	enable/disable	the default setting of a value
bold and arrow	menu → path	menu path in the IGEL setup
bold	GUI [keyboard]	elements of the graphical user interface or commands that are entered using the keyboard
within brackets	[session name]	variable values

W10 IoT Release Notes 18 / 31



Windows 10 IoT

Supported Devices

UD3-W10 50, UD3-W10 51

UD5-W10 50

UD6-W10 51

UD7-W10 10

UD9-W10 40, UD9-W10 Touch 41

W10 IoT Release Notes 19/31



W10 IoT Versions

Drivers

Version
10.18.10.4425 (04/04/2016)
6.16.00.3154 (09/09/2014)
1.1.0.1064 (12/01/2014)
6.0.1.7541 (06/18/2015)
10.014.0123.2017 (01/23/2017)
16.300.2501.0000 (07/26/2016)
1.2.0.0034 (11/08/2015)
2.22.0.0005 (06/27/2016)
2.2.0.57 (04/01/2017)
5.12.0.0031 (04/01/2017)
23.20.808.1280 (02/14/2018)
4.11

Applications	
Citrix Receiver	4.11
Citrix HDX RealTime Media Engine	2.3
Microsoft Internet Explorer	11
Microsoft RDP Client	10.2
NCP Enterprise Client	10.11
Sun JAVA RE	1.8 Update 40
ThinPrint	11.0.120
Tight VNC Server	2.7.10
VMware Horizon Client	4.7.0
Microsoft Windows Media Player	12
Microsoft .NET Framework	4.6
Adobe PDF Reader DC	15.23
FabulaTech USB for Remote Desktop	5.2.3

• Language Packs

W10 IoT Release Notes 20/31



Microsoft-Windows-Client-Language-Pack_x64_de-de.cab
Microsoft-Windows-Client-Language-Pack_x64_es-es.cab
Microsoft-Windows-Client-Language-Pack_x64_fr-fr.cab
Microsoft-Windows-Client-Language-Pack_x64_it-it.cab
Microsoft-Windows-Client-Language-Pack_x64_ja-jp.cab
Microsoft-Windows-Client-Language-Pack_x64_nl-nl.cab

Microsoft Updates

KB4093137

KB4093120

W10 IoT Release Notes 21/31



Known Issues

System

- Start onscreen keyboard at logon does not work.
 - The TC-Setup-Setting Userinterface/Input/Keyboard **Start onscreen keyboard at logon** sets the onscreen keyboard for a logged in user only.
 - Furthermore the **Ease of Access** menu on welcome screen appears delayed and an error message is shown: "Could not start On-Screen keyboard"
- VNC Maintenance screen does not work.
- Snapshot **upload/download via "File" protocol** does not work on UD3/UD7 if the USB device is plugged into a USB 3.0 port.
- Configuration of more than two screens sometimes results in a wrong display order on UD7.

VMware

• When session is started via **Horizon client**, a folder named **GPUcache** appears on the user desktop.

W10 IoT Release Notes 22 / 31



New Features

System

- Added hardware support for **UD7-W10 10**.
- Added hardware support for **UD9-W10 40 and UD9-W10 Touch 41**.
- Added configuration of ${\bf Windows\ activation\ }$ while snapshoting.

More

Registry	firmware_snapshot.activate_windows
Value	enabled / disabled

- Added file transfer of certificate files from UMS.
- Added configuration of custom desktop background picture.

More

IGEL Setup	User Interface > Desktop
Registry	userinterface.customization.use_custom_wallpaper
Value	enabled / <u>disabled</u>
IGEL Setup	User Interface > Desktop
IGEL Setup Registry	User Interface > Desktop userinterface.customization.custom_wallpaper_filename

- Added configuration of ${\bf custom\ boot\ splash\ picture}.$

More

IGEL Setup	System > Firmware Customization > Corporate Design > Custom Bootsplash
Registry	userinterface.customization.use_custom_bootsplash
Value	enabled / <u>disabled</u>
IGEL Setup	System > Firmware Customization > Corporate Design > Custom Bootsplash
IGEL Setup Registry	

Added configuration of Microsoft Windows Defender.
 More

W10 IoT Release Notes 23 / 31



IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.use_igel_setup	
Value	enabled / disabled	
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.enable	
Value	enabled / disabled	
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.definition_download	
Value	enabled / <u>disabled</u>	
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.definition_download_scheduled_timestamp	
Value		
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.definition_download_scheduled_recur_every _days	
Value	<u>1</u>	
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.definition_download_source	
Value	<u>MicrosoftUpdateServer</u>	
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.definition_download_source_file_shares	
Value		
IGEL Setup	Security > Windows Defender	
Registry	system.windows_defender.update_timeout	
Value	<u>600000</u>	

Added Unified Write Filter low overlay watcher.
 More

W10 IoT Release Notes 24/31



Registry	system.uwf.ramcheck_showwarning
Value	enabled / disabled
Registry	system.uwf.ramcheck_threshold
Value	<u>250</u>
Registry	system.uwf.ramcheck_interval_seconds
Valora	
Value	<u>60</u>
Registry	system.uwf.ramcheck_observation_seconds

Citrix

- Added Citrix Receiver version 4.11
- Added Citrix HDX RealTime Media Engine version 2.3

VMware

• Added VMware Horizon client version 4.7.0

FabulaTech

Added FabulaTech USB for Remote Desktop version 5.2.3

W10 IoT Release Notes 25 / 31



Resolved Issues

System

- Fixed IGEL Secure Shadowing does not work.
- Fixed unclear **unjoin domain behaviour**. Client is added to Workgroup "WORKGROUP" after leaving the domain now.
- Fixed **UMS file transfer** without setting a target path does not work (Default target path: C: \Program Files (x86)\IGEL\igel_temp).
- Fixed **after creating a snapshot** with a device registered in UMS and applying it to another device, **same MAC address** is shown in UMS.
- Fixed after a snapshot download old partial update informations will remain in the UMS.
- Fixed **reset to factory defaults** does not work if auto logon is configured.
- Fixed **error in dual screen configuration** when only one monitor is connected.
- Fixed disable USB storage devices does not work.
- Fixed **VNC shadowing** does not work after changing the admin password.
- Fixed watching videos with Microsoft Internet Explorer fills up the Unified Write Filter RAM overlay.

RDP

Fixed configuration of credential saving on connect has no effect.

More

Registry	rdp.winconnect.allowcredentialsaving
Value	enabled / disabled

Citrix

- Fixed **deletion of ICA session** does not delete **session icons** from desktop.
- Fixed **lockdown conflict** "LegacyLocalUserNameAndPassword" after configuring domain passthrough authentication.

VMware

• Fixed VMware session autostart does not work.

W10 IoT Release Notes 26 / 31



Notes for Release 4.01.100

IGEL Universal Desktop W10

Software:	Version	4.01.100
Release Date:	2017-05-15	
Release Notes:	Version	RN-301100-1
Last update:	2017-05-15	

Following formatting is used in this document:

format type	example	use
bold and underlined	enable/disable	the default setting of a value
bold and arrow	menu → path	menu path in the IGEL setup
bold	GUI [keyboard]	elements of the graphical user interface or commands that are entered using the keyboard
within brackets	[session name]	variable values

W10 IoT Release Notes 27 / 31



Windows 10 IoT

Supported Devices

UD5-W10

UD6-W10

W10 IoT Release Notes 28 / 31



W10 IoT Versions

Clients

Product	Version
Intel(R) HD Graphics	10.18.10.4425 (04/04/2016)
Intel(R) Audio	6.16.00.3154 (09/09/2014)
Intel(R) Trusted Execution Engine Interface	1.1.0.1064 (12/01/2014)
Realtek High Definition Audio	6.0.1.7541 (06/18/2015)
Realtek PCIe GBE Family Controller	10.014.0123.2017 (01/23/2017)

Applications

4.7
2.2.100
11
10.2
10.11
1.8 Update 40
11.0.120
2.7.10
4.4.2
12
4.6
15.23

Language Packs

Microsoft-Windows-Client-Language-Pack_x64_de-de.cab
Microsoft-Windows-Client-Language-Pack_x64_es-es.cab
Microsoft-Windows-Client-Language-Pack_x64_fr-fr.cab
Microsoft-Windows-Client-Language-Pack_x64_it-it.cab
Microsoft-Windows-Client-Language-Pack_x64_ja-jp.cab
Microsoft-Windows-Client-Language-Pack_x64_nl-nl.cab

Microsoft Updates

W10 IoT Release Notes 29 / 31



KB3150513		
KB4013418		
KB4015217		
KB4018483		

W10 IoT Release Notes 30 / 31



Known Issues

System

- Start onscreen keyboard at logon does not work.

 The TC-Setup-Setting Userinterface/Input/Keyboard "Start onscreen keyboard at logon" sets the onscreen keyboard for a logged in user only. Furthermore the "Ease of Access" menu on welcome screen shows up delayed and an error message appears: "Could not start On-Screen keyboard"
- VNC Maintenance screen does not work.

W10 IoT Release Notes 31 / 31